





0071230 F5302E60



**FIG. 4**



**FIG. 5**

0071230 F5662E00

FIG. 6




FIG. 7





FIG. 8

FIG. 9





FIG. 10

FIG. 11





FIG. 12

FIG. 13





FIG. 14

00000-15002000

FIG. 15





FIG. 17




FIG. 16

FIG. 18




FIG. 19




FIG. 20




FIG. 21





FIG. 26

FIG. 22





FIG. 23



81G




FIG. 25

81G




FIG. 27

624




FIG. 28






FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 34





FIG. 35






FIG. 36




FIG. 33




FIG. 37




FIG. 39




FIG. 38




FIG. 40




FIG. 41




FIG. 43





FIG. 45






FIG. 47




FIG. 48










FIG. 49



APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		



100379854 00040







FIG. 60




FIG. 60




FIG. 61




FIG. 62




FIG. 64




FIG. 63




FIG. 65




FIG. 67




FIG. 68

001280-15862200






FIG. 69




FIG. 70




FIG. 71




FIG. 72




FIG. 73

1150 1152 1154 1158 1160 1162 1164 1166 1170 1174 1161 1163 1164A 1164B 1164C 1164D 1166A 1166B 1166C 1166D

FIG. 74

10E





FIG. 75



32J




FIG. 76




FIG. 77




FIG. 78







FIG. 79



6040230-15802200

FIG. 80




FIG. 81




FIG. 83




FIG. 82




FIG. 84




FIG. 85




FIG. 86





FIG. 87








FIG. 89

1548A 1548B 1548C 1548D 1548E 1548F 1550A 1550B 1550C 1550D 1550E 1550F

FIG. 90




FIG. 91




FIG. 92




FIG. 91 - P. 33 OF 30

FIG. 93




FIG. 94









FIG. 97



00270954 780400

FIG. 98






FIG. 100

